

Technical Bulletin

Date: August 2009

Type Policy Letter
√Service Information

No: TCM-0040-B
ITCM-0028-B

Page 1 of 1

Attention Service Managers
√Service and Parts Managers

Product AXP / MXP Models

Issue Main Fuse Blown

Warranty Standard product warranty applies.

Action
When main fuse is blown it is required to use Fuse Kit part number 14090030. This kit includes fuse, interlock switch assembly, power relay, and monitor relay board.

Note: Failure to use fuse kit will result in loss of labor payment.

