

Technical Bulletin



Date: July 2010

No: TCM-0054-B
ITCM-0039-B

Type Policy Letter
√Service Information

Page 1 of 1

Attention Service Managers
√Service and Parts Managers

Product AXP20, AXP20JB, AXP20MK, AXP20QT, AXP5201, AXP5203, MXP20, MXP5201, MXP5203

Issue Cracked / Damaged Display

Action Cracked / damaged displays are attributed to misuse or abuse. As per the terms of the warranty, the repair of cracked or damaged display boards are not covered. Product owner is responsible for all costs associated to repair cracked / damaged display.

