

Technical Bulletin



Date: August 2009

Type Policy Letter
√Service Information

No: TCM-0041-B
ITCM-0029-B

Page 1 of 1

Attention Service Managers
√Service and Parts Managers

Product

Model	Manufacturing Number	Model	Manufacturing Number
DECS11MA	P1330217M	RFS12SW2A	P1330208M
DES11EA	P1330218M	RFS511SW2A	P1330223M
DFS11EA	P1330220M	RFS9B2	P1330234M
RCS10A	P1330203M	RS511MB	P1330211M
RCS10DA	P1330201M	RS511P	P1330212M
RCS10MPA	P1330202M	UCS11MA	P1330228M
RCS10MPSA	P1330205M	UFS11EA	P1330230M
RCS10PBDA	P1330204M	URCS511A	P1330226M
RCS511A	P1330214M	URS511MB	P1330224M
RFS10SW2A	P1330232M	URS511P	P1330225M
RFS12MPSA	P1330206M	US11EA	P1330229M

Issue Replacement Interlock Switch Kit

Warranty Standard product warranty applies.

Action

Interlock Switch Kit 14090023 replaces original interlock switch assembly part number 53002001.

The replacement assembly adds a second primary switch in parallel to the first primary. Follow instructions included with Interlock Switch Kit for proper installation.