



Technical Bulletin

Date: June 2009

Type Policy Letter
√Service Information

No: TCM-0039-B
ITCM-0023-B

Page 1 of 1

Attention Service Managers
√Service and Parts Managers

Product

60 hZ Models		50 hZ Models	
RFS12MPSA	P1330206M	DECS11MA	P1330217M
RFS12SW2A	P1330208M	DES11EA	P1330218M
		DFS11EA	P1330220M
		RCS511A	P1330214M
		RFS511SW2A	P1330223M
		RS511MB	P1330211M
		RS511P	P1330212M
		UCS11MA	P1330228M
		UFS11EA	P1330230M
		URCS511A	P1330226M
		URS511MB	P1330224M
		URS511P	P1330225M
		US11EA	P1330229M

Issue New service replacement magnetron 59004083

Warranty Standard product warranty applies.

Action Magnetron 59004083 (Toshiba) is the new service replacement for 53001581 (LG) and 53002002 (Toshiba) for the models listed above.