

Technical Bulletin

MAYTAG®

Date: October 2006

Type Policy Letter
 √ Service Information

No: TCM-0029-B
 ITCM-0020-B
 Page 1 of 1

Attention √ Service Managers
 √ Service and Parts Managers

Brand Amana MenuMaster

Models Amana and MenuMaster Commercial Microwaves Ovens
60 Hz- RCS10DA, RCS10PBDA, RCS10A, RCS10MPA, RCS10MPSA,
RFS9B2, RFS12MPSA, RFS12SW2A, RFS18MPS
50 Hz- DECS11MA, DES11EA, DFS11EA, DFS18E, RCS511A,
RFS511SW2A, RFS518S, RS511P, RS511MB, UCS11MA, UFS11EA,
UFS518E, URCS511A, URFS518S, URS511MB, URS511P, US11EA

Product Com. Microwave

Issue Reinstall Magnetron Bracket after replacing Magnetron.

Warranty Standard product manufacturing warranty applies.

Action When replacing magnetron on these models, the bracket above the magnetron must be reinstalled for air flow purposes. Failure to do so will result in intermittent shut down on the magnetron TCO and / or repeated magnetron failures.

