

Technical Bulletin



Date: January 2020

Type Service and Parts Information

No: TCM-0120-A

Attention Service and Parts Managers

Page 1 of 1

Product RMS10DSE and RMS10TS

Issue Replacement Control Assembly Too Large – Door Will Not Close Properly

Warranty Standard product warranty applies.

Action

If control replacement is necessary on older RMS model / manufacturing numbers, it will be necessary to replace both the control and door assemblies with the newer style components.

Replacing the control only will result in interference issues between the door and the control escutcheon.

Refer to the chart below for the replacement control and door assembly part numbers.

| Original part | | Replacement parts | |
|----------------------|--------------------|--------------------------|--------------------|
| 58101008 | BOARD, HV/LV | 58161096 | CONTROL ASSY- DIAL |
| | | 58161094 | DOOR ASSY- AM |
| 58101009 | BOARD, HV/LV | 58161101 | CONTROL ASSY |
| | | 58161094 | DOOR ASSY- AM |
| 58101010 | BOARD, HV/LV | 58161097 | CONTROL ASSY- DIAL |
| | | 58161095 | DOOR ASSY- MM |
| 58101011 | BOARD, HV/LV | 58161100 | CONTROL ASSY |
| | | 58161095 | DOOR ASSY- MM |
| 58101070 | CONTROL PANEL ASSY | 58161100 | CONTROL ASSY |
| | | 58161095 | DOOR ASSY- MM |