

# Technical Bulletin



Date: October 2011

No: TCM-0070A-B  
Supersedes TCM-0070-B

**Type** Policy Letter  
√Service Information

**Attention** √Service Managers  
Service and Parts Managers

Page 1 of 2

**Product** RC17S2, RC17SD2OSI, MRC17S2, RC22S2, RC30S2, MRC30S2, KFC2W2, WDYRC22, DQ22HSI2, MC23MPW2, MC23MPTW2, ACE14

**Issue** New Components on ACE, RC, KFC, WDYC, DQ, MC product

**Warranty** Standard product warranty applies.

**Action** A new series of manufacturing numbers (P numbers) have been released for the models listed above. The new ACE and MCE models contain a new Interlock Switch, Monitor Relay Board, and Fuse Kit. The RC style ovens contain a new Interlock Switch, Monitor Relay Board, Fuse Kit, and Blower Motor. The new parts listed below **are not interchangeable** with those on older models.

**Caution:** The interlock switch does not have to be changed if the fuse fails. The relay board must be replaced if the fuse fails.

Component	Switch-Interlock	Board, Relay Monitor	Kit, Fuse & Relay Board	Starting at Serial Number
ACE14 P2001901M	59114157	59002117	14119056	1106102744
MCE14 P2001902M	59114157	59002117	14119056	1107101560
ACE14SBC P2001903M	59114157	59002117	14119056	1106102744

<b>Component</b>	<b>Switch-Interlock</b>	<b>Kit, Fuse &amp; Relay Board</b>	<b>Blower Motor</b>	<b>Starting at Serial Number</b>
<b>RC17S2 P2001801M</b>	59114157	14119056	59114158	1108100533
<b>RC17SD2OSI P2001803M</b>	59114157	14119056	59114158	1107101945
<b>MRC17S2 P2001802M</b>	59114157	14119056	59114158	1109102241
<b>RC22S2 P2001804M</b>	59114157	14119056	59114158	1107101969
<b>DQ22HSI2 P2001806M</b>	59114157	14119056	59114158	1107101565

<b>Component</b>	<b>Switch-Interlock</b>	<b>Kit, Fuse &amp; Relay Board</b>	<b>Blower Motor</b>	<b>Starting at Serial Number</b>
<b>RC30S2 P2001811M</b>	59114157	14119056	59114158	1107101658
<b>MRC30S2 P2001812M</b>	59114157	14119056	59114158	1108100654
<b>KFC2W2 P2001810M</b>	59114157	14119056	59114158	1107102322
<b>WDYRC22 P2001809M</b>	59114157	14119056	59114158	1107102334
<b>MC23MPW2 P2001807M</b>	59114157	14119056	59114158	1107100675
<b>MC23MPTW2 P2001808M</b>	59114157	14119056	59114158	1107101428