

# Technical Bulletin

Date: August 2012

No: TCM-0075-S

Page 1 of 1

**Type** Policy Letter  
√Service Information


**Attention** √Service Managers  
Service and Parts Managers

**Product** WDYRC22

**Issue** Location of hidden pads on top touch panel graphics

**Action** Graphics have changed on the WDYRC22 top touch panel. Replacement top touch panels could have either graphic shown below. Note the location of the Hidden Pad, Time Entry Pad and Program Save on the style of touch panel you have.

## Style 1



## Style 2

