

Technical Bulletin



Date: October 2011

No: ITCM-0049A-B
Supersedes ITCM-0049-B

Type Policy Letter
√Service Information

Attention √Service Managers
Service and Parts Managers

Page 1 of 1

Product DS1400E, UCA1400

Issue Change in components on DS1400E, UCA1400 models / unique parts.

Warranty Standard product warranty applies.

Action A new series of manufacturing numbers (P numbers) have been released for the DS1400E and UCA1400 models. The new style ovens contain a new Interlock Switch, Monitor Relay Board and Fuse Kit. The new parts listed below are not interchangeable with those on older models.

Component	DS1400E P2001904M		UCA1400 P2001906M	
Starting @ Serial Number	1108100972		1108101352	
Switch-Interlock	59114157	NEW	59114157	NEW
Board, Relay Monitor	59002117	NEW	59002117	NEW
Kit, Fuse & Relay Board	14119057	NEW	14119057	NEW