

# Technical Bulletin



**Type:** Service information

Date: February 23, 2016

**Attention:** Service and parts managers

No: TCM-0091-B  
ITCM-0068-B

**Product:** CRCS, MCS, and RCS models

**Issue:** New manufacturing numbers / new parts


**Warranty:** Standard product warranty applies

**Action:** ACP has released new manufacturing numbers beginning with mid January 2016 production.

Model #	Manufacturing #
RCS10TS	P2002415M
RCS10DSE	P2002416M
MCS10TS	P2002417M
MCS10DSE	P2002418M
RCS511TS	P2002419M
RCS511DSE	P2002420M
RCS511TSA	P2002421M
RCS511DSEA	P2002422M
RCS511TSU	P2002423M
CRCS511TS	P2002424M
MCS10TSB	P2002425M
MCS10TSSA	P2002426M
MCS10TSP	P2002427M

## Significant changes include:

- 14154101 KIT, SPRING/LATCH/CHOKE COVER  
**NOTE:** This kit is **NOT** backward compatible with 14124068



- 54157099 DOOR ASSY-AM (Amana brand)  
**NOTE:** This assembly **IS** backward compatible with previous manufacturing numbers and will replace 54127020
- 54157101 DOOR ASSY- MM (MenuMaster brand)  
**NOTE:** This assembly **IS** backward compatible with previous manufacturing numbers and will replace 54127022