

Technical Bulletin



Type: Service information

Date: February 23, 2016

Attention: Service and parts managers

No: TCM-0092-B
ITCM-0069-B

Product: MFS and RFS models

Issue: New manufacturing numbers / new parts

Warranty: Standard product warranty applies

Action: ACP has released new manufacturing numbers beginning with mid January 2016 production.

Model #	Manufacturing #
RFS12TSW	P2001017M
RFS12TS	P2001018M
RFS18TS	P2001019M
MFS12TS	P2001020M
MFS18TS	P2001021M
MFS18TSSA	P2001022M

Significant changes include:

- 54157102 LATCH ASSY
NOTE: This assembly **IS** backward compatible with previous manufacturing numbers and will replace 54116005 LATCH ASSEMBLY
- 54157103 SPRING
NOTE: This part **IS** backward compatible with previous manufacturing numbers and will replace 53001780 SPRING
- 14154102 KIT, INTERLOCK SWITCH
NOTE: This kit contains the necessary components to fit old and new manufacturing numbers.

For older manufacturing numbers, the switch assembly in the kit is a drop-in replacement.

For new manufacturing numbers covered in this bulletin, the two primary switches in the assembly must be replaced with the two switches (orange plunger) supplied in the kit. This kit will replace 53002056.

