

Technical Bulletin



Date: February 2010
No: TCM-0049-B

Page 1 of 1

Type Policy Letter
√Service Information

Attention Service Managers
√Service and Parts Managers

Product RFS12 models listed below

Issue New RFS12 model and manufacturing numbers / Unique parts

Warranty Standard product warranty applies

Action

A new series of models and manufacturing numbers (P numbers) have been released for the RFS12 series. The new style ovens contain 2 magnetrons and 2 HV sections. The new parts listed below are not interchangeable with those on older models.

RFS12MPSB replaces RFS12MPSA.
RFS12SW2B replaces RFS12SW2A.

Please see the following list of model and manufacturing numbers along with the new functional parts.

Complete parts illustrations and listings are available on the ACP Services website.

Component	RFS12MPSB P1330235M		RFS12SW2B P1330236M	
Board, HV/LV	53002045	NEW	53002047	NEW
Interlock Switch Assy	53002056	NEW	53002056	NEW
Capacitor, .70	53002038 (qty 2)	NEW	53002038 (qty 2)	NEW
Fuse, 15 A Time Delay	20034001 (qty 2)	NEW	20034001 (qty 2)	NEW
Transformer, HV	53002040 (qty 2)	NEW	53002040 (qty 2)	NEW
Power Cord	53002042	NEW	53002042	NEW
Harness, Main	53002032	NEW	53002032	NEW
Thermal Cutout- Mag	53002034 (qty 2)	NEW	53002034 (qty 2)	NEW
Fuse Assy	53002035 (qty 2)	NEW	53002035 (qty 2)	NEW
Blower Motor Assy	53002049	NEW	53002049	NEW