

Technical Bulletin



Date: July 2020
No: TCM-0720-A
ITCM-0720-A

Type Parts & Service Information

Attention Parts Managers
Service Managers
Service Technicians

Product All 50 & 60hz ARX/MRX & AXP/MXP Xpress Ovens

Issue Melted J5 Connector Requires Entire Wire Harness Replacement

Action Use Recently Created J5 Connector Kit Part # 59204719

Warranty Standard Manufacturer's Warranty Applies.

This kit is designed to replace any AXP/MXP or ARX/MRX Xpress Ovens with a damaged J5 Connector. Simply install the new connector, orient the old connector with the locking tab facing up and splice wires one at a time. Be certain to route wiring away from any hot or moving components. Kit comes with wire ties.

