

Technical Bulletin



Date: January 2010
No: TCM-0047-B
ITCM-0033-B
Page 1 of 1

Type Policy Letter
√Service Information

Attention Service Managers
√Service and Parts Managers

Product AXP20*, AXP5201, MXP5201, AXP5203, MXP5203 Models

Issue Line(s) in the Display


Action

Should you encounter a complaint of line(s) in the display on an AXP / MXP model, have the customer unplug and plug unit back in. This may clear the fault, however, should the line(s) return the filter board will need to be replaced.

Some early production ovens produced prior to June 2008, with serial number prefix 0805 and earlier, may not have a filter board. If the oven does not have a filter board contact ComServ for assistance.

Phone: 866.426.2621

Email: commercialservice@acpsolutions.com



AXP / MXP with line(s) in the display