

# Technical Bulletin



**Type:** Service Information

Date: 4/29/2015

**Attention:** Service and Parts Managers

No.: TCM0088-B  
ITCM0065-B

**Product:** Compact Microwave Oven Models with Various "P" Numbers

**Issue:** New HV/LV Board Kits and Replacement Parts

**Warranty:** Standard product warranty applies

**Action:** The original factory equipped HV/LV board on various model/manufacturing numbers of compact models substitutes to replacement kits including HV/LV board and harness adapter.

Refer to the following information for the affected model/manufacturing numbers and replacement part information after kits have been installed.

## 50 Hz Models

Model #	Mfg/BOM	Replacement HV board kit
CDEC14E2	P1331230M	14159091
CDEC18E2	P1331231M	14159091
CHDC5142	P1331227M	14159091
CHDC5182	P1331228M	14159091
CHDC5182	P1331249M	14159091
DEC11E2	P1331213M	14159091
DEC11E2	P1331235M	14159091
DEC14E2	P1331217M	14159091
DEC14E2	P1331239M	14159091
DEC18E2	P1331221M	14159091
DEC18E2	P1331243M	14159091
DEC21E2	P1331226M	14159091
DEC21E2	P1331247M	14159091
HDC12P2	P1331223M	14159091
HDC5112	P1331211M	14159091
HDC5112	P1331233M	14159091
HDC5142	P1331215M	14159091
HDC5142	P1331237M	14159091

Model #	Mfg/BOM	Replacement HV board kit
HDC5182	P1331219M	14159091
HDC5182	P1331241M	14159091
HDC5212	P1331224M	14159091
HDC5212	P1331245M	14159091
MCHDC521	P1331225M	14159091
MCHDC521	P1331246M	14159091
UC11E2	P1331214M	14159091
UC11E2	P1331236M	14159091
UC14E2	P1331218M	14159091
UC14E2	P1331240M	14159091
UC18E2	P1331222M	14159091
UC18E2	P1331244M	14159091
UHDC5112	P1331212M	14159091
UHDC5112	P1331234M	14159091
UHDC5142	P1331216M	14159091
UHDC5142	P1331238M	14159091
UHDC5182	P1331220M	14159091
UHDC5182	P1331242M	14159091

## Service Replacement Parts

If the unit has a replacement HV/LV board kit installed, refer to the information below for parts included in the replacement kits.

<b>Component</b>	<b>Replacement part with Kit 14159091 installed</b>
HV/LV board	59004111
Adapter harness	20136401