

Technical Bulletin



Date: November 2009

No: TCM-0044-B

Page 1 of 1

Type Policy Letter
√Service Information

Attention Service Managers
√Service and Parts Managers

Product ALD10D, ALD10T models

Issue New Manufacturing Numbers (P numbers)

Warranty Standard product warranty applies.

Action ACP has released two new P numbers for the ALD10D and ALD10T models. The change involves the blower motor and the HV transformer. The new parts **ARE NOT** interchangeable with the old parts. Refer to the following chart for the unique parts for each P number:

	ALD10D P1331011M	ALD10D P1331019M	ALD10T P1331002M	ALD10T P1331018M
Blower Motor Assembly	56001411	56002020	56001411	56002020
HV Transformer	56001437	56002021	56001437	56002021